


Aircraft owners have relied on Honeywell's Maintenance Service Plan (MSP) for decades to give them the industry's best and most flexible APU service plan. Now, Honeywell offers expanded coverage for 36-150, RE220, RE100 and 36-100 model APU's.



Business

Aviation's

Most

Comprehensive

APU



Maintenance

Program

Now Offers

Enhanced

Protection



MSP Gold

Honeywell



**Maintenance
Service Plan
Gold Program**

Honeywell Aerospace
Business & General Aviation
P.O. Box 29003
Phoenix, AZ 85038-9003
Tel: 602.365.3181
Fax: 602.365.5313
www.honeywell.com

Honeywell

A60-0859-000-001
February 2011
© 2011 Honeywell International

MSP GOLD expands your standard MSP coverage to include many of the additional charges often associated with APU repairs. The MSP GOLD extended coverage includes items such as:

→ **APU and LRU removal and reinstallation labor**

→ **APU freight in and freight out expenses**

→ **Access time**

→ **Extended troubleshooting allowances**

→ **Routine inspection labor**

→ **The cost of road trips when AOG due to an apu problem anywhere in the world**

All of these additional coverages and more are available under MSP GOLD for a nominal increase to the standard MSP hourly rate.

Examples of items not covered by MSP or MSP GOLD: Items not contained in APU IPC such as airframe parts and fluids (oil, fuel, etc.); overtime; expedite fees; transportation of components other than APU's and LRU's; labor for ECU downloading; Service Center administration fees for logbook review, material control, freight for internal workorders, etc.; or any service not provided by a Honeywell Authorized Service Center.

Honeywell's MSP/APU GOLD... *Extended Coverage*

	Covered Items	MSP Gold
Scheduled Maintenance		
■ Routine Periodic Inspection		
Consumable parts	✓	✓
Other required parts	✓	✓
Component repair labor (if required)	✓	✓
*Inspection labor (when accomplished by a Honeywell Service Center)		✓
■ Combustion and Exhaust (HOT) Section Periodic Inspections		
Consumable parts	✓	✓
Other required parts	✓	✓
Component repair labor (if required)	✓	✓
Inspection labor (when accomplished by a Honeywell Authorized Service Center)	✓	✓
*APU and LRU removal and reinstallation and/or access time		✓
*Transportation of APU or LRU		✓
■ Unscheduled Maintenance		
***Troubleshooting labor allowance (up to 10 hours)	✓ (up to 20 hours)	✓
Consumable parts	✓	✓
Other required parts	✓	✓
Component repair labor (if required)	✓	✓
Exchange apu/module/line replaceable unit (LRU)	✓	✓
Rental APU (from Honeywell APU bank at special MSP rates)	✓	✓
*APU and LRU removal and reinstallation and/or access time		✓
***Logistical support for road trips (APU AOG only), (Optional)		✓
*Transportation of unserviceable APU or LRU		✓
APU Modernization Programs		
■ Alert Service Bulletins		
Parts	✓	✓
Labor	✓	✓
■ Recommended Service Bulletins		
Parts	✓	✓
Labor**	✓	✓

* Per MSP standard business practices

** Labor will be covered by MSP when bulletins are incorporated in conjunction with other MSP covered maintenance activities providing convenient access to the applicable engine area.

*** As required with approval